Scope of	Work for Property Loc	cated a	at:		3354 North 30th Street				
	Property is: Single Far	nily [	<b>√</b>	Duplex	□ Other □	_			
Date:	7/21/2011								
take no respo	onsibility for problems discovered	after the	insp	ection date	. The City of Milwaukee, the Redevelopment Authority, and their ree, or for omissions through error or oversight. The list does not need all Block Grant or HOME programs.				
Exterior	Condition Report								
Location Site	Required Work Landscaping	n/a		Yes 🗸	Note/Comments Self Helpremove brush \$	Cost 500.00			
	Steps/Handrails	n/a	<b>√</b>	Yes 🗌	\$				
	Service walks	n/a	<b>√</b>	Yes 🗌	\$				
	Fencing	n/a		Yes 🗹	Repair sections as needed \$	500.00			
	Parking	n/a	<b>√</b>	Yes 🗌	\$				
	Retaining walls	n/a [	<b>√</b>	Yes 🗌	\$				
	Other	n/a		Yes $\square$	\$				
	Other	n/a		Yes 🗌	\$				
Garage	Singles: repair	n/a	7	Yes 🗌	\$				
	Shingles: Roof over existing	n/a	<b>4</b>	Yes 🗌	\$				
	Shingles:Tear off & re-roof			Yes 🗸	\$	4,360.00			
	Gutters/downspouts	n/a	<b>√</b>	Yes	\$	· ·			
	Flashing	n/a	<b>4</b>	Yes	\$				
	Eaves	n/a		Yes 🗸	\$	420.00			
	Siding	n/a		Yes ☑	repair \$	500.00			
	Doors	n/a	<b>4</b>	Yes 🗌	\$				
	Windows	n/a		Yes ☑	Board over \$	300.00			
	Slab	n/a	<b>√</b>	Yes	\$				
	Paint	n/a		Yes 🗸	\$	250.00			
	Electrical	n/a	<b>√</b>	Yes 🗌	\$				
	Other	n/a		Yes 🗌	\$				
Porches	Roof	n/a	<b>4</b>	Yes 🗌	\$				
	Deck-upper		<b>√</b>	Yes	\$				
	Decklower		<b>√</b>	Yes	\$				
	Steps/handrails			Yes 🗸	Front porch \$	750.00			
	Ceiling		<u>√</u>	Yes	\$				
	Guardrails		<b>√</b>	Yes	\$				
	Structural		<b>√</b>	Yes	\$				
	Paint			Yes $\square$	\$				

n/a  $\ \square$  Yes  $\ \checkmark$  Storm Windows

Other

400.00

\$

## House

Chimney	n/a ✓	Yes 🗌		\$ 
Shingles: repair	n/a ☑	Yes 🗌		\$ 
Shingles: Roof over existing	n/a ✓	Yes 🗌		\$
Shingles:Tear off & re-roof	n/a □	Yes ☑		\$ 6,540.00
Gutters/downspouts	n/a 🗌	Yes ☑		\$ 756.00
Flashing	n/a ☑	Yes 🗌		\$ 
Eaves	n/a 🗌	Yes ☑	repair as necessary	\$ 467.00
Siding	n/a 🗌	Yes ☑	repair as necessary	\$ 500.00
Storm Doors	n/a 🗌	Yes ☑	front and rear	\$ 530.00
Prime ("main") Doors	n/a 🗌	Yes ✓	front and rear	\$ 700.00
Storm Windows	n/a ☑	Yes 🗌		\$ 
Prime ("main") Windows	n/a 🗌	Yes ☑	all	\$ 3,720.00
Paint	n/a ☑	Yes 🗌		\$ 
Foundation	n/a ☑	Yes 🗌		\$
Electrical	n/a ☑	Yes 🗌		\$ 
Other	n/a 🗌	Yes ☑	Remove illegal basement & 2nd floor occupancy	\$ 2,000.00
Other	n/a 🗌	Yes 🗌		\$ 
Other	n/a 🗌	Yes 🗌		\$ 
Other	n/a 🗌	Yes 🗌		\$

Exterior: Estimated Cost:\*

23,193.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report						
	Unit: Entire unit (single family) Upper unit of duplex	✓				Lower unit of duplex  Other	
Mechanical Heating	Required Work	_	_	_			
	Repair/replace boiler	n/a L	<u> </u>	es L			\$ 
	Repair radiation	n/a 🕒	7 Y	es [			\$ 
	Repair/replace furnace	n/a	_ Y	es [	<b>√</b>		\$ 3,000.00
	Repair ductwork	n/a	] Y	es [	<b>4</b>		\$ 286.00
	Replace thermostat	n/a	] Y	es [	<b>√</b>		\$ 100.00
	Repair/replace grilles	n/a	] Y	es [	<b>√</b>		\$ 150.00
Electrical	Tune boiler/furn. insp ht exchange	∉n/a [	/ Y	es [			\$ 
Licotrical	Repair/replace receptacles	n/a 🔄	/ Y	es [			\$ 
	Repair/replace switches	n/a 🕒	/ Y	es [			\$
	Repair/replace fixtures	n/a 🛭	7 Y	es [			\$
	Install outlets and circuits	n/a	] Y	es [	<b>√</b>	GFIC as required	\$ 400.00
	Install outlets and circuits	n/a 🖸	7 Y	es [			\$
	Install outlets and circuits	n/a 🖸	7 Y	es [			\$
	Install outlets and circuits	n/a 🗔	7 Y	es [			\$ 
	Upgrade service	n/a [	] Y	es [	<b>7</b>	replace	\$ 1,756.00
	Other	n/a	] Y	es [	<b>4</b>	ensure all circuits operate	\$ 1,000.00
Di alta	Other	n/a [	] Y	es [			\$ 
Plumbing	Repair/replace kitchen sink	n/a [	] Y	es [	<b>4</b>	Complete Kitchen	\$ 1,455.00
	Repair/replace kitchen sink fauce	n/a [	] Y	es [			\$ 
	Repair/replace tub	n/a	] Y	es [	<b>√</b>	Complete Bath	\$ 2,170.00
	Repair/replace tub faucet	n/a	] Y	es [			\$ 
	Repair/replace toilet	n/a	] Y	es [			\$
	Repair/replace lavatory	n/a [	] Y	es [			\$
	Repair/replace lavatory faucet	n/a [	] Y	es [			\$
	Repair/replace wash tub	n/a [	] Y	es [	<b>√</b>		\$ 619.00
	Repair/replace wash tub faucet	n/a [	] Y	es [	<b>4</b>		\$ 315.00
	Unclog piping:	n/a	] Y	es [			\$
	Repair drain/waste/vent piping	n/a	] Y	es [	<b>√</b>		\$ 220.00
	Repair water piping	n/a [	] Y	es [	<b>4</b>		\$ 309.00
	Repair/replace water heater	n/a [	] Y	es [	<b>4</b>		\$ 800.00
	Other	n/a [	] Y	es [			\$

Other n/a Yes \$

Windows								
	Replace broken glass	n/a	J	Yes			\$	
	Repair or replace sash	n/a	<b>4</b>	Yes			\$	
Doors	Repair or replace doors	n/a		Yes	7	as needed	\$	500.00
	Repair or repl. locks/latches	n/a	<b>7</b>	Yes		Self Help	\$	
Walls/Ceiling	gs Repair or repl. @ defective	n/a		Yes	7	patch as needed	\$	1,416.00
Paint	Repair or repl. @ defective	n/a	П	Yes	<b>V</b>		\$	320.00
Fire Safety								
i no outery	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>4</b>	Self Help	\$	40.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>4</b>	Self Help	\$	40.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	<b>4</b>	Self Help	\$	40.00
Handrails	Repair/replace defective	n/a	7	Yes		Self Help	\$	
Stairs	Repair defective	n/a	—— П	Yes	[7]	Repair basement stairs	\$	864.00
Floors	Repair defective	n/a		Yes	<u> </u>	Kitchen and bath floors	\$	1,500.00
Other	ricpaii derective	11/4		100	<u> </u>	Tationer and San Hoors	Ψ	1,000.00
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	17,300.00
						Total Exterior and Interior Cost:*	\$	40,493.00

Inspected by: Chris Buzzell Date: 07/21/2011

## **Self Help**

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.